



Upraviteljica v postopkih zaradi
insolventnosti in prisilnega
prenehanja ČADRAMSKA VAS 23
2319 POLJČANE
email: claudia.ambroz@gmail.com
safe electronic mailbox:
klavdija.ambroz@vep.si

Pursuant to the decision by District Court Slovenj Gradec, ref. no. 272/2021, of 28.7.2021, for the bankruptcy debtor

RAVNE PRESSES, družba za proizvodnjo stiskalnic, strojnih delov in naprav d. o. o., Ravne na Koroškem, Koroška cesta 015, 2390 Ravne na Koroškem

THE BANKRUPTCY TRUSTEE PUBLISHES
A MINIMUM-BID PUBLIC AUCTION

I. DESCRIPTION OF THE PROPERTY

Subject to sale:

1. Trade mark no. 201070910, active until 15.06.2030
2. Trade mark no. 201570448, active until 09.04.2025
3. Trade mark no. 201770986, active until 28.08.2027
4. All plans, archive/know-how

II. MINIMUM BID AND SECURITY DEPOSIT The minimum bid is set as follows:

- 10.500,00 euro for the property under point 1
- 10.700,00 euro for the property under point 2
- 15.000,00 euro for the property under point 3
- 552.000,00 euro for the property under point 4

Security for the subjects to sale shall be set at 10% of the minimum bid as follows:

- 1.050,00 euro for the property under point 1,
- 1.070,00 euro for the property under point 2,
- 1.500,00 euro for the property under point 3,
- 55.200,00 euro for the property under point 4.

in each subsequent step, the minimum bid may be raised by 1,000.00 EUR, beside the offered price, tax, costs of ownership transfer, and all other possible costs are charged to the buyer.

III. CONDITIONS OF PUBLIC AUCTION

- The property is being sold on 'as-is' basis, therefore the bankruptcy debtor is not accountable for material or legal defects of the property which is the subject to sale.
- By approaching the auction, the buyer confirms the knowledge of the subject to sale. The potential buyers may view the subject to sale and the associated documentation prior to public auction, therefore any complaints relating to lack of knowledge of the subjects to sale and possible missing documentation shall be ignored.

- Public auction is open to natural persons who are citizens of the Republic of Slovenia or legal persons in the Republic of Slovenia and foreign natural and legal persons under conditions of reciprocity.
- Before the auction, all bidders shall pay security in the above mentioned amounts. The bidders shall transfer security payment to the bankruptcy debtor's bank account **SI5664000000028335, BIC HKVISI22 (Primorska hranilnica d.d.) with the purpose »security deposit for trade marks/know how«**, no later than one workday before the public auction. Bids may be placed only by those who paid the security or submitted a bank guarantee, or an inflow of security payment is unambiguously noted in the bankruptcy debtor's bank account, or the auctioneer will check the security payment on their website.
- Security deposit shall be given back to the unsuccessful bidders, interest-free, in three days after the conclusion of the public auction.
 - The buyer has to pay earnest money as a sign that the contract has been concluded. In accordance with Article 333, Paragraph 6 of ZFPPIPP, the security payment of a successful buyer, who concludes the contract, is considered earnest payment as a sign that the contract has been concluded.
 - A successful buyer's security payment is recognised as earnest money confirming the conclusion of the sales contract.
 - The bidder who is successful at auction is obliged to conclude the sales contract which shall be drawn in accordance with the provisions set in ZFPPIPP within 3 workdays. In case the bidder does not comply with provisions set under this point, the paid earnest money is included in the bankrupt's estate.
 - Deadline for the settling of the purchase price shall not be longer than 3 months after the conclusion of the sales contract.
 - If the payment of sales sum is late by more than 15 days after the deadline, the bankruptcy debtor may terminate the contract without giving the buyer another deadline for completion of the contract (payment of sales sum). In such case earnest money shall be included in the bankrupt's estate. The buyer may decline the payment of sales sum until the court's decision on the consent to the sales contract becomes final.
 - The sales contract is concluded under suspensory condition, which means that the court shall give its consent to the contract, and under resolatory condition which is met if the court does not give its consent.
 - With the payment of the sales sum and associated costs, the rights of the third parties to property which is the subject to sale cease.
 - The transfer of property to the buyer's proprietary possession shall be made after the prior payment of complete sales price, taxes, and sales costs. For completing the transfer of the subject to sale into the buyer's proprietary possession, provisions from Article 342, Paragraphs 2 and 3 of ZFPPIPP shall be considered. After the payment of sales price and on a proposal from the bankruptcy trustee, the court issues a decision on delivery to the buyer, by which it confirms that all conditions for the transfer/delivery of the property have been met.
 - The minimum price does not include any fiscal charge or general government charges. These are paid solely by the buyer and are included in the sales price. General government charges and taxes, in accordance with the legislation in force, as well as costs connected to the conclusion of the sales contract and transfer of ownership, are paid by the buyer.
 - If one or more bidders approach the auction and none of them, despite having paid earnest money, offers the minimum price or places a bid, it is considered that all of them have withdrawn from the auction and the bankruptcy debtor keeps the security as forfeit money.
 - The participant who did not succeed at public auction, creditor, beneficiary with the pre-emptive right or the third party is not entitled, neither in bankruptcy proceedings nor in any other proceeding, to seek the enforcement for revocation or declaration of annulment of the sales contract, for the conclusion of sales contract under the same conditions with it, for revocation or declaration of annulment of legal transaction of disposal, with which the right to property or any other property right was transferred to the buyer, or for any other claim, the enforcement of which interferes with the rights which the buyer acquires with the conclusion or completion of the sales contract.
 - A buyer cannot be a person who is not allowed to conclude the contract in accordance with the provisions set in Article 337 of ZFPPIPP, except the beneficiary with pre-emptive right, who claims their legal pre-emptive right in accordance with ZFPPIPP. A written declaration

confirming there are no impediments for concluding the contract stemming from Article 337, paragraph 1 of ZFPPIPP shall be submitted by the buyer before the conclusion of the contract.

- The beneficiary with pre-emptive right is obliged to claim the potential pre-emptive right at public auction in accordance with Article 347 of ZFPPIPP.
- For questions which are not explicitly set in this invite, the provisions from ZFPPIPP and other regulations shall be directly applicable, according to the conditions of the sale.

- The sales contract shall be concluded under suspensory condition that the court shall give its consent to the contract, and under resolutive condition which is met if the court does not give its consent to the sales contract, and under suspensory condition regarding the finality of Decision on delivery of property and resolutive condition if the decision on the delivery of the real estate is not final.

III. RULES OF PUBLIC AUCTION

- The bankruptcy debtor authorised NetBid GmbH, Vienna, to execute the public auction and market the units (subject to sale), and to publish the marketing of bankruptcy debtor's units on website <http://www.netbid.com>.
- Further details and methods of bidding shall be published by the company NetBid GmbH, Vienna, on website <http://www.netbid.com>.
- The auction shall take place via online platform NetBid GmbH <http://www.netbid.com>, which keeps record of every bidder's step.
- The marketing on the company's website shall be based on general business conditions which have been agreed on and are applicable to the sale of Ravne Presses d.o.o. – bankrupt's property and shall be published on website <http://www.netbid.com>, where the bankruptcy debtor bears no costs for the sale via the before-mentioned company within the agreed terms of sale and marketing of the subject to sale.
- The successful bidder shall be notified by the bankruptcy trustee on the time of conclusion of the written contract, which shall not be longer than three workdays after the conclusion of the auction. If the bidder does not sign the contract within this period of time, the bankruptcy debtor is entitled to contractual penalty due to failure to fulfil obligations in the sum equal to the sum of earnest money.
- The property is sold by the bankruptcy trustee under the provisions set in Articles 329 and 343 of ZFPPIP.
- The participant who did not succeed at public auction or in the process of public bidding, creditor, beneficiary with the pre-emptive right, or the third party is not entitled, neither in bankruptcy proceedings nor in any other proceeding, to seek the enforcement for revocation or declaration of annulment of the sales contract, for the conclusion of sales contract under the same conditions with it, for revocation or declaration of annulment of legal transaction of disposal, with which the right to property or any other property right was transferred to the buyer, or any other claim, the enforcement of which interferes with the rights which the buyer acquires with the conclusion or completion of the sales contract.

The public auction for the sale of trade marks and archive is open from 20.9.2021 to 24.9.2021 until 2 pm. The auction takes place in accordance with terms and conditions set by the company NetBid, published on website www.netbid.com.

All information regarding the property are available from the representative of NetBid GmbH, Mr Aleš Weiksler, who can be contacted every workday by phone: +386 40 515 140 or via email: weiksler@netbid.com, and on website <http://www.netbid.com>. Inspection of the property is possible by prior arrangement with a NetBid GmbH representative.

For general information please contact the Bankruptcy Trustee, email claudia.ambroz@gmail.com, or Velunšek Miran, phone number 070 521 515.

Bankruptcy Trustee
Klavdija Ambrož, MSc

Registered trademark

(111) Registration number: **201070910**

(151) Date of registration: 23.03.2011

(180) Valid until: 15.06.2030

(210) Applications number 201070910

(220) Date of registration: 15.06.2010

(300) Pre-emptive right: - - - - -

(441) Publication of application: 29.10.2010

(450) Publication of registration: 29.04.2011

(511) Nice Classification: **7, 35, 37, 42**

(531) Vienna Classification: 27.5.1,3,10; 29.1.1,6

(591) Colour indication: grey, orange (CMYK: 36-26-16-0, 58-59-47-14, 0-60-100-0)

(731) Applicant: *see (732)*

(732) Holder: **Litostroj Ravne, a company for the production of presses, machine parts and**

Machinery d.o.o., Koroška cesta 14, 2390 Ravne na Koroškem, SI (Slovenia) (510,511) List of goods/services:

07: Machinery and machine tools; engines (except for land vehicles); clutches and drive parts (except for land vehicles); agricultural machinery (except for hand-operated); rollers; mechanical and hydraulic presses.

35: advertising; commercial management; business administration; office & commercial operations; marketing; marketing; sale of machinery and machine tools, engines (other than for land vehicles), clutches and drive parts (other than for land vehicles), agricultural machinery (other than hand-operated), rollers, mechanical and hydraulic presses.

37: Repair; installation services; installation and servicing of presses, machinery and plant.

42: scientific, technological and research and design services - design services in connection therewith; industrial analysis and research; development of presses, machinery and apparatus.



Registered trade mark

Registration number: 201570448

Date of registration: 30.12.2015

(180) Valid until: 09.04.2025

(210) Application No: 201570448

(220) Date of registration: 09.04.2015

(300) Prior right: - - - - -

(441) Publication of the application: 31.08.2015

(450) Publication of registration: 29.02.2016

(511) Nice Classification: 7, 35, 37, 42

(731) Applicant: See

(732) Proprietor: Litostroj Ravne, company for the manufacture of presses, machine parts and d.o.o., Koroška cesta 15, 2390 Ravne na Koroškem, SI (Slovenia) (510,511)



List of goods/services:

07: Machinery and machine tools: Pistons (parts of engines or machines); pistons for shock absorbers (parts of machines); pistons for vibration dampers (parts of machines); pistons for engines; pistons for cylinders; piston rings; drums (parts of machines); driving wheels for machines; driving wheels for machines; shafts for machines; hydraulic control gears for engines and machines; universal joints for machines; control gears for machines and engines; bearing bushings; tables for machines; motors other than for land vehicles, bearing supports (for machines); machine frames; machine housings; connecting rods for machines and motors; feeders (parts of machines); gear reducers other than for land vehicles; clutches other than for land vehicles; mechanical and hydraulic presses (machines for industrial use); trimming machines; cutting machines; bending machines; drawing machines (metal); conveyors (machines).

35: Advertising; commercial management; business administration; office administration.

37: installation, maintenance and repair of machinery; reconditioning of worn-out or damaged machinery; installation and servicing of presses, machinery and plant.

42: Scientific and technological services and research and related design services; industrial analysis and research; design and development of computer hardware and software; provision of legal assistance.

Registered trade mark

(111) Registration number: 201770986

(151) Date of registration: 06.04.2018

(180) Valid until: 28.08.2027

(210) Application No: 201770986

(220) Date of registration: 28.08.2017

(300) Prior right: - - - - -

(441) Publication of the application: 30.10.2017

(450) Publication of registration: 31.05.2018

(511) Nice Classification: 7, 35, 37, 42

(531) Vienna Classification: 26.4.2,22; 27.5.1; 29.1.1,6

(591) Indication of colours: grey, orange, white

(731) Applicant: see (732)

(732) Proprietor: RAVNE PRESSES d.o.o., Koroška cesta 15, 2390 Ravne na Koroškem, SI (Slovenia)



(510,511) List of goods/services:

07: Machinery and machine tools: pistons (parts of engines or machines); pistons for shock absorbers (parts of machines); pistons for vibration dampers (parts of machines); pistons for engines; pistons for cylinders; piston rings; drums (parts of machines); driving wheels for machines; driving wheels for machines; shafts for machines; hydraulic control gears for engines and machines; universal joints; control gears for machines and engines; bearing bushings; tables for machines; motors other than for land vehicles, bearing supports (for machines); machine frames; machine housings; connecting rods for machines and motors; feeders (parts of machines); gear reducers other than for land vehicles; clutches other than for land vehicles; mechanical and hydraulic presses (machines for industrial use); trimming machines; cutting machines; bending machines; drawing machines (metal); conveyors (machines).

35: Advertising; commercial management; business administration; office administration.

37: installation, maintenance and repair of machinery; reconditioning of worn-out or damaged machinery; installation and servicing of presses, machinery and plant.

42: Scientific and technological services and research and related design services; industrial analysis and research; design and development of computer hardware and software.

Additional information:

International Registration No: WO 1416619

STISKALNICE mehanske

| Zap. št. | N. št. | Tip | Nazivna sila (kN) | Leto izdelave | IN. (ON.) | Strojna projekcija (evidenca dokumentacije) | N. št. |
|----------|------------|-----------|-------------------|---------------|-----------|---|------------|
| 1 | 9 701 00 | EE-100 | 1000 | 1973 | | ročna | 9 701 00 |
| 2 | 9 701 01 | EE-100 | 1000 | 1975 | | ročna | 9 701 01 |
| 3 | 9 701 03 | EE-100 | 1000 | 1976 | | ročna | 9 701 03 |
| 4 | 9 701 04 | EE-100 | 1000 | 1980 | | ročna | 9 701 04 |
| 5 | 9 701 05 | DEE-100 | 1000 | 1984 | | ročna | 9 701 05 |
| 6 | 9 701 06 | EDE-100 | 1000 | 1983 | | ročna | 9 701 06 |
| 7 | 9 701 06/A | EDE-100 | 1000 | 1990 | | ročna | 9 701 06/A |
| 8 | 9 701 07 | SPM-16 | | 1984 | | ročna | 9 701 07 |
| 9 | 9 701 07/A | SPM-16 | | 1993 | | ročna | 9 701 07/A |
| 10 | 9 701 07/C | SPM-16 | | 1993 | | ročna | 9 701 07/C |
| 11 | 9 701 07/1 | SPM-16 | | 1995 | | ročna | 9 701 07/1 |
| 12 | 9 701 08 | EDE-100 | 1000 | 1995 | | ročna | 9 701 08 |
| 13 | 9 701 09 | PPK-16 | | 1985 | | ročna | 9 701 09 |
| 14 | 9 701 10 | DEE-100 | 1000 | 1985 | | ročna | 9 701 10 |
| 15 | 9 701 11 | VPS-100 | 1000 | 1987 | | ročna | 9 701 11 |
| 16 | 9 701 12 | EE-40 | 400 | 1987 | | ročna | 9 701 12 |
| 17 | 9 701 13 | EE-100 | 1000 | 1987 | | ročna | 9 701 13 |
| 18 | 9 701 14 | EE-80 | 800 | 1987 | | ročna | 9 701 14 |
| 19 | 9 701 15 | EDE-100 | 1000 | 1988 | | ročna | 9 701 15 |
| 20 | 9 701 16 | VPS-100 | 1000 | 1988 | | ročna | 9 701 16 |
| 21 | 9 701 17 | RAM-85 | | 1990 | | ročna | 9 701 17 |
| 22 | 9 701 18 | RAM-55 | | 1990 | | ročna | 9 701 18 |
| 23 | 9 701 19 | VZS-120 | | 1990 | | ročna | 9 701 19 |
| 24 | 9 701 20 | RAM-55 | | 1990 | | ročna | 9 701 20 |
| 25 | 9 701 21 | RAM-125 | | 1992 | | ročna | 9 701 21 |
| 26 | 9 701 22 | EDE-100 | 1000 | 1991 | | ročna | 9 701 22 |
| 27 | 9 701 23 | RAM-85H+R | | 1991 | | ročna | 9 701 23 |
| 28 | 9 701 24 | RAM-85H | | 1991 | | ročna | 9 701 24 |
| 29 | 9 701 25 | RAM-55H+R | | 1991 | | ročna | 9 701 25 |
| 30 | 9 701 26 | RAM-55H | | 1991 | | ročna | 9 701 26 |
| 31 | 9 701 27 | RCM-55 | | 1991 | | ročna | 9 701 27 |
| 32 | 9 701 28 | RCM-85 | | 1991 | | ročna | 9 701 28 |
| 33 | 9 701 29 | RCM-125 | | 1991 | | ročna | 9 701 29 |
| 34 | 9 701 30 | RAM-55 | | 1991 | | ročna | 9 701 30 |
| 35 | 9 701 31 | DEE-100 | 1000 | 1991 | | ročna | 9 701 31 |
| 36 | 9 701 32 | RCM-55 | | 1991 | | ročna | 9 701 32 |
| 37 | 9 701 33 | RLC-125 | | 1991 | | ročna | 9 701 33 |
| 38 | 9 701 34 | RLC-160 | | 1991 | | ročna | 9 701 34 |
| 39 | 9 701 35 | RAM-55 | | 1991 | | ročna | 9 701 35 |
| 40 | 9 701 36 | RAM-85 | | 1991 | | ročna | 9 701 36 |
| 41 | 9 701 37 | RAM-85 | | 1991 | | ročna | 9 701 37 |
| 42 | 9 701 38 | RLC-100 | 1000 | 1991 | | ročna | 9 701 38 |

| | | | | | | | |
|----|----------|-----------|------|------|--------------|------------|----------|
| 43 | 9 701 39 | RLC-63 | | 1991 | | ročna | 9 701 39 |
| 44 | 9 701 40 | RLC-100E | 1000 | 1992 | | ročna | 9 701 40 |
| 45 | 9 701 41 | RCM-100 | 1000 | 1992 | | ročna | 9 701 41 |
| 46 | 9 701 42 | RLC-100 | 1000 | 1992 | | ročna | 9 701 42 |
| 47 | 9 701 44 | VPS-100 | 1000 | 1992 | | ročna | 9 701 44 |
| 48 | 9 701 45 | RLC-100 | 1000 | 1992 | | ročna | 9 701 45 |
| 49 | 9 701 46 | RLC-63 | | 1992 | | ročna | 9 701 46 |
| 50 | 9 701 47 | RLC-100 | 1000 | 1992 | | ročna | 9 701 47 |
| 51 | 9 701 48 | RLC-160 | | 1992 | | ročna | 9 701 48 |
| 52 | 9 701 49 | SPM-20 | | 1994 | | ročna | 9 701 49 |
| 53 | 9 701 50 | SMS-6 | | 1994 | | ročna | 9 701 50 |
| 54 | 9 701 51 | RLC-100 | 1000 | 1994 | | ročna | 9 701 51 |
| 55 | 9 701 52 | RLC-63 | | 1994 | | ročna | 9 701 52 |
| 56 | 9 701 53 | RLC-63 | | 1994 | | ročna | 9 701 53 |
| 57 | 9 701 54 | RLC-63 | | 1994 | | ročna | 9 701 54 |
| 58 | 9 701 55 | RLC-100 | 1000 | 1994 | | ročna | 9 701 55 |
| 59 | 9 701 56 | RLC-63 | | 1994 | | ročna | 9 701 56 |
| 60 | 9 701 57 | RLC-63 | | 1994 | | ročna | 9 701 57 |
| 61 | 9 701 58 | VPS-100 | 1000 | 1994 | | ročna | 9 701 58 |
| 62 | 9 701 59 | RLC-100 | 1000 | 1994 | | ročna | 9 701 59 |
| 63 | 9 701 60 | SC2-5 | | 1995 | | ročna | 9 701 60 |
| 64 | 9 701 61 | RLC-100 | | 1995 | | ročna | 9 701 61 |
| 65 | 9 701 62 | TPA-45 | | | | ročna | 9 701 62 |
| 66 | 9 701 63 | VPS-100 | 1000 | 1996 | ON.70048 | ročna | 9 701 63 |
| 67 | 9 701 64 | SPM-20-3 | | 1996 | | ročna | 9 701 64 |
| 68 | 9 701 65 | SPM-100-3 | 1000 | 1996 | | ročna | 9 701 65 |
| 69 | 9 701 66 | SC2-100 | 1000 | 1997 | ON.80013 | ročna/acad | 9 701 66 |
| 70 | 9 701 68 | SC1-80 | 800 | 1997 | ON.80069 | ročna/acad | 9 701 68 |
| 71 | 9 701 69 | SPM-20 | | 1997 | | ročna | 9 701 69 |
| 72 | 9 701 70 | SPM-16 | | 1998 | | ročna | 9 701 70 |
| 73 | 9 701 71 | SC2-100 | 1000 | 1998 | ON.90043 | ročna/acad | 9 701 71 |
| 74 | 9 701 72 | SC2-100 | 1000 | 1998 | ON.90042 | ročna/acad | 9 701 72 |
| 75 | 9 701 73 | SPM-125-3 | 1000 | 1999 | ON.10027 | ročna | 9 701 73 |
| 76 | 9 701 74 | C1-100 | 1000 | 1999 | ON.10074 | acad | 9 701 74 |
| 77 | 9 701 75 | C1-100 | 1000 | 2000 | ON.10075 | acad | 9 701 75 |
| 78 | 9 701 76 | C1-100 | 1000 | 2000 | ON.20064 | ročna/acad | 9 701 76 |
| 79 | 9 701 76 | C1-100 | 1000 | 2002 | ON.40013 | ročna/acad | 9 701 76 |
| 80 | 9 701 77 | C1-100 | 1000 | 2001 | ON.30001 | acad | 9 701 77 |
| 81 | 9 701 77 | C1-100 | 1000 | 2001 | ON.30041 | acad | 9 701 77 |
| 82 | 9 701 78 | SC2-100 | 1000 | 2001 | ON.20077 | ročna/acad | 9 701 78 |
| 83 | 9 701 79 | C1-100 | 1000 | 2002 | | acad | 9 701 79 |
| 84 | 9 701 80 | C1-100 | 1000 | 2002 | ON.40070 | acad | 9 701 80 |
| 85 | 9 701 81 | C1-80 | 800 | 2004 | ON.60008 | acad | 9 701 81 |
| 86 | 9 701 82 | C1-80 | 800 | 2005 | ON.60186 | acad | 9 701 82 |
| 87 | 9 701 83 | SE2-100 | 1000 | 2007 | IN.200700037 | acad | 9 701 83 |
| 88 | 9 701 84 | C1-80 | 800 | 2007 | IN.200700217 | acad | 9 701 84 |
| 89 | 9 702 00 | KES-160 | 1600 | 1974 | | ročna | 9 702 00 |
| 90 | 9 702 01 | KES-160 | 1600 | 1976 | | ročna | 9 702 01 |
| 91 | 9 702 02 | HKS-160 | 1600 | 1977 | | ročna | 9 702 02 |
| 92 | 9 702 03 | DE-160 | 1600 | 1979 | | ročna | 9 702 03 |
| 93 | 9 702 04 | DE-160 | 1600 | 1979 | | ročna | 9 702 04 |
| 94 | 9 702 05 | DE-160 | 1600 | 1979 | | ročna | 9 702 05 |

| | | | | | | | |
|-----|------------|---------------|------|------|--------------|------------|------------|
| 95 | 9 702 06 | DE-160 | 1600 | 1980 | | ročna | 9 702 06 |
| 96 | 9 702 07 | UHS-150 | 1500 | 1988 | | ročna | 9 702 07 |
| 97 | 9 702 08 | UHS-150 (170) | 1500 | 1990 | | ročna | 9 702 08 |
| 98 | 9 702 08/1 | UHS-150 (170) | 1500 | 1995 | ON.60053 | ročna | 9 702 08/1 |
| 99 | 9 702 09 | SC2-160 | 1600 | 1996 | ON.80001 | ročna/acad | 9 702 09 |
| 100 | 9 702 10 | SC2-125 | 1250 | 1998 | ON.90031 | ročna/acad | 9 702 10 |
| 101 | 9 702 11 | C1-125 | 1250 | 2001 | | ročna/acad | 9 702 11 |
| 102 | 9 702 12 | SC2-125 | 1250 | 2002 | ON.30066 | acad | 9 702 12 |
| 103 | 9 702 13 | C1-125 | 1250 | 2003 | ON.50001 | acad | 9 702 13 |
| 104 | 9 702 14 | C1-125 | 1250 | 2007 | IN.200700218 | acad | 9 702 14 |
| 105 | 9 702 15 | C1-125 | 1250 | 2007 | IN.200700218 | acad | 9 702 15 |
| 106 | 9 702 16 | C1-125 | 1250 | 2007 | IN.200700218 | acad | 9 702 16 |
| 107 | 9 702 17 | C1-125 | 1250 | 2007 | IN.200700218 | acad | 9 702 17 |
| 108 | 9 702 18 | SC2-125 | 1250 | 2008 | IN.200800213 | acad | 9 702 18 |
| 109 | 9 703 00 | VPS-200 | 2000 | 1990 | | ročna | 9 703 00 |
| 110 | 9 703 01 | VPS-200 | 2000 | 1993 | | ročna | 9 703 01 |
| 111 | 9 703 02 | SC2-200 | 2000 | 1994 | | ročna | 9 703 02 |
| 112 | 9 703 03 | SC2-200 | 2000 | 1995 | ON.60019 | ročna | 9 703 03 |
| 113 | 9 703 04 | SC2-200 | 2000 | 1995 | | ročna | 9 703 04 |
| 114 | 9 703 05 | RLC-200 | 2000 | 1996 | | ročna | 9 703 05 |
| 115 | 9 703 06 | SC2-200 | 2000 | 1997 | ON.80043 | ročna/acad | 9 703 06 |
| 116 | 9 703 07 | SC2-200 | 2000 | 2000 | ON.20073 | acad | 9 703 07 |
| 117 | 9 703 08 | SC2-200 | 2000 | 2001 | | acad | 9 703 08 |
| 118 | 9 704 00 | KES-250 | 2500 | 1972 | | ročna | 9 704 00 |
| 119 | 9 704 01 | DE-250 | 2500 | 1972 | | ročna | 9 704 01 |
| 120 | 9 704 02 | KES-250 | 2500 | 1974 | | ročna | 9 704 02 |
| 121 | 9 704 03 | KES-250 | 2500 | 1974 | | ročna | 9 704 03 |
| 122 | 9 704 04 | DE-250 | 2500 | 1975 | | ročna | 9 704 04 |
| 123 | 9 704 05 | DE-250 | 2500 | 1975 | | ročna | 9 704 05 |
| 124 | 9 704 06 | KES-250 | 2500 | 1976 | | ročna | 9 704 06 |
| 125 | 9 704 07 | HKS-250 | 2500 | 1976 | | ročna | 9 704 07 |
| 126 | 9 704 08 | DE-250 | 2500 | 1977 | | ročna | 9 704 08 |
| 127 | 9 704 09 | DE-250 | 2500 | 1977 | | ročna | 9 704 09 |
| 128 | 9 704 10 | DE-250 | 2500 | 1980 | | ročna | 9 704 10 |
| 129 | 9 704 11 | DE-250 | 2500 | 1987 | | ročna | 9 704 11 |
| 130 | 9 704 12 | DE-250 | 2500 | 1980 | | ročna | 9 704 12 |
| 131 | 9 704 13 | VPS-250 | 2500 | 1983 | | ročna | 9 704 13 |
| 132 | 9 704 14 | DEE-250 | 2500 | 1984 | | ročna | 9 704 14 |
| 133 | 9 704 15 | UHS-250 | 2500 | 1984 | | ročna | 9 704 15 |
| 134 | 9 704 16 | DEE-250 | 2500 | 1986 | | ročna | 9 704 16 |
| 135 | 9 704 17 | VPS-250 | 2500 | 1986 | | ročna | 9 704 17 |
| 136 | 9 704 17/1 | VPS-250 | 2500 | 1990 | | ročna | 9 704 17/1 |
| 137 | 9 704 18 | DE-250 | 2500 | 1987 | | ročna | 9 704 18 |
| 138 | 9 704 19 | EDE-250 | 2500 | 1990 | | ročna | 9 704 19 |
| 139 | 9 704 20 | UHS-250 | 2500 | 1990 | | ročna | 9 704 20 |
| 140 | 9 704 21 | VPS-250 | 2500 | 1990 | | ročna | 9 704 21 |
| 141 | 9 704 21/1 | VPS-250 | 2500 | 1991 | | ročna | 9 704 21/1 |
| 142 | 9 704 22 | SC2-250 | 2500 | 1995 | ON.60029 | ročna | 9 704 22 |
| 143 | 9 704 23 | SC2-250 | 2500 | 1997 | ON.80035 | ročna/acad | 9 704 23 |
| 144 | 9 704 24 | SC2-250 | 2500 | 1998 | ON.80092 | ročna/acad | 9 704 24 |
| 145 | 9 704 25 | SC2-250 | 2500 | 2000 | ON.20069 | ročna/acad | 9 704 25 |
| 146 | 9 704 26 | C1-250 | 2500 | 2002 | ON.50001 | acad | 9 704 26 |

| | | | | | | | |
|-----|------------|-----------|------|------|--------------|------------|------------|
| 147 | 9 704 27 | SC2-250 | 2500 | 2004 | ON.60003 | acad | 9 704 27 |
| 148 | 9 704 28 | SE4-250 | 2500 | 2005 | ON.70005 | acad | 9 704 28 |
| 149 | 9 704 29 | SC2-250 | 2500 | 2007 | ON.80016 | acad | 9 704 29 |
| 150 | 9 704 30 | SE2-250 | 2500 | 2007 | IN.200700181 | acad | 9 704 30 |
| 151 | 9 704 31 | C1-250 | 2500 | 2007 | IN.200700218 | acad | 9 704 31 |
| 152 | 9 705 01 | DE-315 | 3150 | 1977 | | ročna | 9 705 01 |
| 153 | 9 705 02 | DE-315 | 3150 | 1979 | | ročna | 9 705 02 |
| 154 | 9 705 02/1 | DE-315 | 3150 | 1979 | | ročna | 9 705 02/1 |
| 155 | 9 705 04 | DE-315 | 3150 | 1980 | | ročna | 9 705 04 |
| 156 | 9 705 05 | DE-315 | 3150 | 1987 | | ročna | 9 705 05 |
| 157 | 9 705 06 | DE-315 | 3150 | 1980 | | ročna | 9 705 06 |
| 158 | 9 705 07 | DE-315 | 3150 | 1981 | | ročna | 9 705 07 |
| 159 | 9 705 08 | UHS-315 | 3150 | 1984 | | ročna | 9 705 08 |
| 160 | 9 705 09 | DE-315 | 3150 | 1985 | | ročna | 9 705 09 |
| 161 | 9 705 10 | DE-315 | 3150 | 1985 | | ročna | 9 705 10 |
| 162 | 9 705 11 | DE-315 | 3150 | 1985 | | ročna | 9 705 11 |
| 163 | 9 705 13 | DE-315 | 3150 | 1989 | | ročna | 9 705 13 |
| 164 | 9 705 14 | DE-315 | 3150 | 1995 | ON.60011 | ročna/acad | 9 705 14 |
| 165 | 9 705 15 | DE-315 | 3150 | 1996 | ON.70063 | ročna | 9 705 15 |
| 166 | 9 705 16 | SC2-315 | 3150 | 1998 | ON.90077 | ročna/acad | 9 705 16 |
| 167 | 9 705 17 | SC2-320 | 3200 | 1999 | ON.90092 | ročna/acad | 9 705 17 |
| 168 | 9 705 18 | SC1-300 | 3200 | 2000 | ON.10075 | acad | 9 705 18 |
| 169 | 9 705 19 | SE2-315 | 3150 | 2000 | ON.20070 | acad | 9 705 19 |
| 170 | 9 705 20 | SC2-315 | 3150 | 2002 | ON.50000 | acad | 9 705 20 |
| 171 | 9 705 21 | C1-315 | 3150 | 2003 | ON.50001 | acad | 9 705 21 |
| 172 | 9 705 22 | SC2-320 | 3200 | 2004 | ON.60001-2 | acad | 9 705 22 |
| 173 | 9 705 23 | SC1-300 | 3000 | 2004 | ON.60008 | acad | 9 705 23 |
| 174 | 9 705 24 | SC1-300 | 3000 | 2004 | ON.60008 | acad | 9 705 24 |
| 175 | 9 705 25 | SC1-300 | 3000 | 2004 | ON.60186 | acad | 9 705 25 |
| 176 | 9 705 26 | SC1-300 | 3000 | 2004 | ON.60186 | acad | 9 705 26 |
| 177 | 9 705 27 | SE4-315 | 3150 | 2005 | ON.70005 | acad | 9 705 27 |
| 178 | 9 705 28 | SL1-300 | 3000 | 2005 | ON.70006 | acad | 9 705 28 |
| 179 | 9 705 29 | SE2-315 | 3150 | 2006 | ON.80011 | acad | 9 705 29 |
| 180 | 9 705 30 | SC1-300 | 3000 | 2008 | IN.200700217 | acad | 9 705 30 |
| 181 | 9 705 31 | SC1-300 | 3000 | 2008 | IN.200700217 | acad | 9 705 31 |
| 182 | 9 705 32 | C1-315 | 3150 | 2008 | IN.200700218 | acad | 9 705 32 |
| 183 | 9 705 33 | C1-315 | 3150 | 2008 | IN.200700218 | acad | 9 705 33 |
| 184 | 9 705 34 | C1-315 | 3150 | 2008 | IN.200700218 | acad | 9 705 34 |
| 185 | 9 706 00 | KES-400 | 4000 | 1974 | | ročna | 9 706 00 |
| 186 | 9 706 01 | KES-400 | 4000 | 1975 | | ročna | 9 706 01 |
| 187 | 9 706 02 | DE-400 | 4000 | 1979 | | ročna | 9 706 02 |
| 188 | 9 706 03 | DEE-400 | 4000 | 1983 | | ročna | 9 706 03 |
| 189 | 9 706 04 | KES-400 | 4000 | 1986 | | ročna | 9 706 04 |
| 190 | 9 706 05 | DA400/250 | 4000 | | | ročna | 9 706 05 |
| 191 | 9 706 06 | DE-400 | 4000 | | | ročna | 9 706 06 |
| 192 | 9 706 09 | 2DE-400 | 4000 | 1991 | | ročna | 9 706 09 |
| 193 | 9 706 10 | 2DE-400 | 4000 | | | ročna | 9 706 10 |
| 194 | 9 706 11 | VPS-400 | 4000 | 1991 | | ročna | 9 706 11 |
| 195 | 9 706 12 | DE-400 | 4000 | | | ročna | 9 706 12 |
| 196 | 9 706 13 | UHS-400 | 4000 | 1992 | | ročna | 9 706 13 |
| 197 | 9 706 14 | UHS-400 | 4000 | 1993 | | ročna | 9 706 14 |
| 198 | 9 706 15 | SC2-400 | 4000 | 1996 | ON.70008 | ročna | 9 706 15 |

| | | | | | | | |
|-----|------------|------------|------|-------------|--------------|------------|------------|
| 199 | 9 706 16 | SC2-400 | 4000 | 1997 | ON.90026 | ročna/acad | 9 706 16 |
| 200 | 9 706 17 | SC2-400 | 4000 | 1999 | ON.10073 | acad | 9 706 17 |
| 201 | 9 706 18 | SC2-400 | 4000 | 2000 | ON.10075 | acad | 9 706 18 |
| 202 | 9 706 19 | SC2-400 | 4000 | 2001 | ON.30001 | acad | 9 706 19 |
| 203 | 9 706 20 | SC2-400 | 4000 | 2001 | ON.30001 | acad | 9 706 20 |
| 204 | 9 706 19 | SC2-400 | 4000 | 2001 | ON.30041 | acad | 9 706 19 |
| 205 | 9 706 20 | SC2-400 | 4000 | 2001 | ON.30041 | acad | 9 706 20 |
| 206 | 9 706 21 | SC2-400 | 4000 | 2002 | ON.40070 | acad | 9 706 21 |
| 207 | 9 706 22 | SC2-400 | 4000 | 2004 | ON.50012 | acad | 9 706 22 |
| 208 | 9 706 23 | P2E2Sq.400 | | 2005 | ON.70002 | acad | 9 706 23 |
| 209 | 9 706 24 | SC2-400 | 4000 | 2006 | IN.200700034 | acad | 9 706 24 |
| 210 | 9 706 25 | SE2-400 | 4000 | 2006 | ON.80007 | acad | 9 706 25 |
| 211 | 9 706 26 | SE2-400 | 4000 | 2006 | ON.80008 | acad | 9 706 26 |
| 212 | 9 706 27 | SC2-400 | 4000 | 2006 | ON.80010 | acad | 9 706 27 |
| 213 | 9 706 28 | SC1-400 | 4000 | 2007 | IN.200700035 | acad | 9 706 28 |
| 214 | 9 706 29 | SC1-400 | 4000 | 2007 | IN.200700036 | acad | 9 706 29 |
| 215 | 9 706 30 | SE2-400 | 4000 | 2007 | IN.200700003 | acad | 9 706 30 |
| 216 | 9 706 30 | SE2-400 | 4000 | 2007 | IN.200700004 | acad | 9 706 30 |
| 217 | 9 706 31 | SC2-400 | 4000 | 2007 | IN.200700217 | acad | 9 706 31 |
| 218 | 9 706 32 | SE2-400 | 4000 | 2008 | IN.200800256 | acad | 9 706 32 |
| 219 | 9 707 00 | DE-500 | 5000 | 1974 | | ročna | 9 707 00 |
| 220 | 9 707 01 | DE-500 | 5000 | 1975 | | ročna | 9 707 01 |
| 221 | 9 707 02 | DE-500 | 5000 | 1975 | | ročna | 9 707 02 |
| 222 | 9 707 03 | DE-500 | 5000 | 1976 | | ročna | 9 707 03 |
| 223 | 9 707 04 | DE-500 | 5000 | 1976 | | ročna | 9 707 04 |
| 224 | 9 707 04/1 | DE-500 | 5000 | 1978 | | ročna | 9 707 04/1 |
| 225 | 9 707 05 | DE-500 | 5000 | 1977 | | ročna | 9 707 05 |
| 226 | 9 707 06 | DE-500 | 5000 | 1977 | | ročna | 9 707 06 |
| 227 | 9 707 07 | DE-500 | 5000 | 1978 | | ročna | 9 707 07 |
| 228 | 9 707 07/1 | DE-500 | 5000 | | | ročna | 9 707 07/1 |
| 229 | 9 707 08 | DA-500/300 | 5000 | 1978 | | ročna | 9 707 08 |
| 230 | 9 707 08/1 | DA-500/300 | 5000 | | | ročna | 9 707 08/1 |
| 231 | 9 707 09 | DE-500 | 5000 | 1981 | | ročna | 9 707 09 |
| 232 | 9 707 10 | DE-500 | 5000 | 1986 | | ročna | 9 707 10 |
| 233 | 9 707 12 | DA-500/300 | 5000 | 1987 | | ročna | 9 707 12 |
| 234 | 9 707 13 | DE-500 | 5000 | 1990 | | ročna | 9 707 13 |
| 235 | 9 707 14 | VPS-500 | 5000 | 1991 | | ročna | 9 707 14 |
| 236 | 9 707 15 | DA-400/250 | 5000 | nedokončano | | ročna | 9 707 15 |
| 237 | 9 707 16 | 2DE-500 | 5000 | nedokončano | | ročna | 9 707 16 |
| 238 | 9 707 17 | DA-500/300 | 5000 | nedokončano | | ročna | 9 707 17 |
| 239 | 9 707 18 | UHS-500 | 5000 | 1992 | | ročna | 9 707 18 |
| 240 | 9 707 19 | UHS-500 | 5000 | 1993 | | ročna | 9 707 19 |
| 241 | 9 707 20 | SC2-500 | 5000 | 1998 | ON.90055 | ročna/acad | 9 707 20 |
| 242 | 9 707 21 | SE4-500 | 5000 | 2000 | ON.10080 | acad | 9 707 21 |
| 243 | 9 707 22 | SE4-500 | 5000 | 2000 | ON.10081 | acad | 9 707 22 |
| 244 | 9 707 23 | SC2-500 | 5000 | 2002 | ON.40027 | acad | 9 707 23 |
| 245 | 9 707 24 | SC2-500 | 5000 | 2002 | ON.40070 | acad | 9 707 24 |
| 246 | 9 707 25 | SE2-500 | 5000 | 2003 | ON.50006-7 | acad | 9 707 25 |
| 247 | 9 707 26 | Muller-500 | | 2005 | ON.70002 | acad | 9 707 26 |
| 248 | 9 707 27 | SC2-500 | 5000 | 2005 | ON.70011 | acad | 9 707 27 |
| 249 | 9 707 28 | SE2-500 | 5000 | 2007 | ON.80006 | acad | 9 707 28 |
| 250 | 9 707 29 | SE2-500 | 5000 | 2007 | IN.200700005 | acad | 9 707 29 |

| | | | | | | | |
|-----|------------|--------------------|-------|------|--------------|------------|------------|
| 251 | 9 707 30 | SC2-500 | 5000 | 2007 | IN.200700183 | acad | 9 707 30 |
| 252 | 9 708 00 | KES-630 | 6300 | 1972 | | ročna | 9 708 00 |
| 253 | 9 708 01 | KES-630 | 6300 | 1975 | | ročna | 9 708 01 |
| 254 | 9 708 02 | VZV-630V | 6300 | 1978 | | ročna | 9 708 02 |
| 255 | 9 708 03 | DEE-630 | 6300 | 1982 | | ročna | 9 708 03 |
| 256 | 9 708 04 | HKS-630 | 6300 | 1982 | | ročna | 9 708 04 |
| 257 | 9 708 05 | VZS-630 | 6300 | 1983 | | ročna | 9 708 05 |
| 258 | 9 708 07 | HKS-630 | 6300 | 1986 | | ročna | 9 708 07 |
| 259 | 9 708 08 | DE-600 | 6000 | 1987 | | ročna | 9 708 08 |
| 260 | 9 708 09 | DE-630 | 6300 | 1988 | | ročna | 9 708 09 |
| 261 | 9 708 10 | 2DE-630 | 6300 | 1989 | | ročna | 9 708 10 |
| 262 | 9 708 11 | DE-600 | 6000 | 1989 | | ročna | 9 708 11 |
| 263 | 9 708 12 | DE-600 | 6000 | 1991 | | ročna | 9 708 12 |
| 264 | 9 708 13 | DE-630 | 6300 | 1993 | | ročna | 9 708 13 |
| 265 | 9 708 13/1 | DE-630 | 6300 | 1993 | | ročna | 9 708 13/1 |
| 266 | 9 708 14 | UHS-600 | 6000 | 1994 | | ročna | 9 708 14 |
| 267 | 9 708 15 | S2-600 | 6000 | 1994 | ON.60002 | ročna | 9 708 15 |
| 268 | 9 708 16 | S4-600 | 6000 | 1995 | ON.60031 | ročna | 9 708 16 |
| 269 | 9 708 17 | SC2-600 | 6000 | 1997 | ON.80003 | ročna/acad | 9 708 17 |
| 270 | 9 708 18 | SE4-600 | 6000 | 1997 | ON.80016 | ročna/acad | 9 708 18 |
| 271 | 9 708 19 | SL2-630 | 6300 | 1998 | ON.80093 | acad | 9 708 19 |
| 272 | 9 708 20 | SC2-600 | 6000 | 2001 | ON.30025 | acad | 9 708 20 |
| 273 | 9 708 21 | SE2-630 | 6300 | 2001 | ON.30045 | acad | 9 708 21 |
| 274 | 9 708 22 | SC2-630 | 6300 | 2001 | ON.30056 | acad | 9 708 22 |
| 275 | 9 708 23 | | | | | acad | 9 708 23 |
| 276 | 9 708 24 | SC2-600 | 6000 | 2005 | ON.60004 | acad | 9 708 24 |
| 277 | 9 708 25 | SC2-600 | 6000 | 2005 | ON.60005 | acad | 9 708 25 |
| 278 | 9 708 26 | SE4-600 | 6000 | 2005 | ON.60010 | acad | 9 708 26 |
| 279 | 9 708 27 | SE2-630 | 6300 | 2006 | | acad | 9 708 27 |
| 280 | 9 708 28 | SE2-630 | 6300 | 2006 | | acad | 9 708 28 |
| 281 | 9 708 29 | DQ600.36.50 | | 2005 | ON.70002 | acad | 9 708 29 |
| 282 | 9 709 01 | DEE-800 | 8000 | 1979 | | ročna | 9 709 01 |
| 283 | 9 709 01A | DEE-800 | 8000 | 1979 | | ročna | 9 709 01A |
| 284 | 9 709 03 | DE-800 | 8000 | 1982 | | ročna | 9 709 03 |
| 285 | 9 709 05 | DE-800 | 8000 | 1988 | | ročna | 9 709 05 |
| 286 | 9 709 06 | 2DE-800 | 8000 | 1989 | | ročna | 9 709 06 |
| 287 | 9 709 07 | SE4-800 | 8000 | 1994 | ON.50014 | ročna | 9 709 07 |
| 288 | 9 709 09 | S4-800 | 8000 | 1994 | ON.50015 | ročna | 9 709 09 |
| 289 | 9 709 10 | D4-800/600 | | 1995 | ON.60034 | ročna/acad | 9 709 10 |
| 290 | 9 709 11 | SE4-800 | 8000 | 1999 | ON.10002-4 | acad | 9 709 11 |
| 291 | 9 709 12 | SE4-800 | 8000 | 1999 | ON.10082 | acad | 9 709 12 |
| 292 | 9 709 13 | SC2-800 | 8000 | 2002 | ON.40082 | acad | 9 709 13 |
| 293 | 9 709 14 | DA-500/300-SE2-630 | | 2003 | ON.50008 | acad | 9 709 14 |
| 294 | 9 709 15 | SE2-800 | 8000 | 2005 | ON.50013 | acad | 9 709 15 |
| 295 | 9 709 16 | SE2-800 | 8000 | 2006 | ON.80068 | acad | 9 709 16 |
| 296 | 9 709 17 | SE2-800 | 8000 | 2007 | ON.80009 | acad | 9 709 17 |
| 297 | 9 709 18 | SE2-800 | 8000 | 2007 | IN.200700006 | acad | 9 709 18 |
| 298 | 9 709 19 | SE2-800 | 8000 | 2008 | IN.200800162 | acad | 9 709 19 |
| 299 | 9 710 01 | VKS-1000 | 10000 | 1981 | | ročna | 9 710 01 |
| 300 | 9 710 02 | DEE-1000 | 10000 | 1982 | | ročna | 9 710 02 |
| 301 | 9 710 03 | HKS-1000 | 10000 | 1982 | | ročna | 9 710 03 |
| 302 | 9 710 04 | DEE-1000 | 10000 | 1983 | | ročna | 9 710 04 |

| | | | | | | | |
|-----|------------|------------|-------|------|--------------|------------|------------|
| 303 | 9 710 05 | 2DE-1000 | 10000 | 1985 | | ročna | 9 710 05 |
| 304 | 9 710 06 | DEE-1000 | 10000 | 1986 | | ročna | 9 710 06 |
| 305 | 9 710 07 | DA-600/400 | 10000 | 1988 | | ročna | 9 710 07 |
| 306 | 9 710 08 | KES-1000 | 10000 | 1988 | | ročna | 9 710 08 |
| 307 | 9 710 09 | 2DE-900 | 9000 | 1988 | | ročna | 9 710 09 |
| 308 | 9 710 10 | 2DE-900 | 9000 | 1988 | | ročna | 9 710 10 |
| 309 | 9 710 11 | DA-600/400 | 10000 | 1989 | | ročna | 9 710 11 |
| 310 | 9 710 12 | 2DE-1250 | 12500 | 1990 | | ročna | 9 710 12 |
| 311 | 9 710 14 | SE4-1000 | 10000 | 1994 | ON.50016 | ročna | 9 710 14 |
| 312 | 9 710 14/1 | SE4-1000 | 10000 | 1997 | ON.70040 | ročna | 9 710 14/1 |
| 313 | 9 710 16 | SE4-1000 | 10000 | 1997 | ON.80077 | ročna/acad | 9 710 16 |
| 314 | 9 710 16/1 | SE4-1000 | 10000 | 1998 | | ročna/acad | 9 710 16/1 |
| 315 | 9 710 17 | SE4-1000 | 10000 | 1999 | ON.10005 | ročna/acad | 9 710 17 |
| 316 | 9 710 17/1 | SE4-1000 | 10000 | 1998 | | ročna/acad | 9 710 17/1 |
| 317 | 9 710 18 | SE4-1000 | 10000 | 1999 | ON.10001 | acad | 9 710 18 |
| 318 | 9 710 20 | SE4-1000 | 10000 | 2005 | ON.70003 | acad | 9 710 20 |
| 319 | 9 710 21 | VK-1000 | | 2005 | ON.70002 | acad | 9 710 21 |
| 320 | 9 710 22 | DB2-1000 | | 2005 | ON.70002 | acad | 9 710 22 |
| 321 | 9 710 23 | DA-630/400 | | 2007 | ON.80002 | acad | 9 710 23 |
| 322 | 9 710 24 | SE2-1000 | 10000 | 2007 | ON.80005 | acad | 9 710 24 |
| 323 | 9 711 01 | DEE-1250 | 12500 | 1978 | | ročna | 9 711 01 |
| 324 | 9 711 02 | DEE-1250 | 12500 | 1978 | | ročna | 9 711 02 |
| 325 | 9 711 03 | DEE-1250 | 12500 | 1980 | | ročna | 9 711 03 |
| 326 | 9 711 04 | DEE-1250 | 12500 | 1981 | IN.200700176 | ročna | 9 711 04 |
| 327 | 9 711 05 | 2DE-1250 | 12500 | 1990 | | ročna | 9 711 05 |
| 328 | 9 711 06 | 2DE-1250 | 12500 | 1993 | ON.40003 | ročna | 9 711 06 |
| 329 | 9 711 07 | SE2-1200 | 12000 | 2003 | ON.50010 | acad | 9 711 07 |
| 330 | 9 711 08 | VK-1250 | | 2005 | ON.70002 | acad | 9 711 08 |
| 331 | 9 711 09 | SE2-1200 | 12000 | 2007 | IN.200700184 | acad | 9 711 09 |
| 332 | 9 712 01 | SE2-1500 | 15000 | 1997 | ON.80040 | ročna/acad | 9 712 01 |
| 333 | 9 712 02 | SE4-1500 | 15000 | 1998 | ON.90086 | ročna/acad | 9 712 02 |
| 334 | 9 712 03 | SE2-1500 | 15000 | 1999 | ON.10006 | ročna/acad | 9 712 03 |
| 335 | 9 712 04 | SE4-1500 | 15000 | 2003 | ON.50002 | acad | 9 712 04 |
| 336 | 9 713 01 | SC2-1600 | 16000 | 1997 | ON.80004 | ročna/acad | 9 713 01 |
| 337 | 9 713 01 | SC2-1600 | 16000 | 1998 | ON.80073 | ročna/acad | 9 713 01 |
| 338 | 9 713 01 | SC2-1600 | 16000 | 1998 | ON.90036 | ročna/acad | 9 713 01 |
| 339 | 9 713 01 | SC2-1600 | 16000 | 2000 | ON.20029 | ročna/acad | 9 713 01 |
| 340 | 9 713 02 | SC2-1600 | 16000 | 2000 | ON.20029 | acad | 9 713 02 |
| 341 | 9 713 03 | SE4-1600 | 16000 | 2003 | ON.50009 | acad | 9 713 03 |
| 342 | 9 715 02 | S4-2000 | 20000 | 1994 | ON.50017 | ročna/acad | 9 715 02 |
| 343 | 9 715 03 | SE2-2000 | 20000 | 2001 | ON.30019 | acad | 9 715 03 |
| | | | | | IN.201600027 | | |
| 344 | 9 715 04 | SE4-2000 | 20000 | 2005 | ON.70008 | acad | 9 715 04 |
| 345 | 9 715 05 | SE4-2000 | 20000 | 2007 | IN.200700118 | acad | 9 715 05 |
| 346 | 9 717 01 | SE2-2500 | 25000 | 1999 | ON.10020 | acad | 9 717 01 |
| 347 | 9 717 01 | SE2-2500 | 25000 | 2007 | IN.200700046 | acad | 9 717 01 |
| 348 | 9 717 02 | SE4-2500 | 25000 | 1999 | ON.10060 | acad | 9 717 02 |
| 349 | 9 717 03 | MW-ZS-2300 | | 2005 | ON.70002 | acad | 9 717 03 |
| 350 | 9 718 01 | SE4-3000 | 30000 | 2005 | ON.70009 | acad | 9 718 01 |
| 351 | 9 721 01 | S4-4000 | 40000 | 1996 | ON.70030 | ročna/acad | 9 721 01 |
| 352 | 9 709 20 | PE4-HH 800 | 8000 | 2009 | IN.200900218 | acad | 9 709 20 |
| 353 | 9 711 10 | SL4-1400 | 14000 | 2010 | IN.201000182 | acad | 9 711 10 |

| | | | | | | | |
|-----|------------|--------------------|-------|------|--------------|---------|------------|
| 354 | 9 711 03 | SE2-1250 | 12500 | 2010 | IN.201000239 | acad | 9 711 03 |
| 355 | 9 702 19 | SCSV2-160 | 1600 | 2010 | IN.201000217 | acad | 9 702 19 |
| 356 | 9 706 33 | SE2-400 | 4000 | 2010 | IN.201000417 | acad | 9 706 33 |
| 357 | 9 704 32 | SC1-250 | 2500 | 2010 | IN.201000xxx | acad | 9 704 32 |
| 358 | 9 709 14 | DA-500/300-SE2-630 | | 2010 | IN.201000718 | acad | 9 709 14 |
| 359 | 9 701 85 | SC2-80 | 800 | 2010 | IN.201000737 | acad | 9 701 85 |
| 360 | 9 717 04 | SE4-2500 | 25000 | 2011 | IN.201100072 | acad | 9 717 04 |
| 361 | 9 710 25 | SE4-1000 | 10000 | 2011 | IN.201100071 | acad | 9 710 25 |
| 362 | 9 703 09 | SC2-200 | 2000 | 2012 | IN.201200070 | acad | 9 703 09 |
| 363 | 9 706 34 | SK1-400 | 4000 | 2012 | IN.201200228 | acad | 9 706 34 |
| 364 | 9 708 30 | SE1-630 | 6300 | 2012 | IN.201200362 | acad | 9 708 30 |
| 365 | 9 711 11 | SE2-1200 | 12000 | 2012 | IN.201200420 | acad | 9 711 11 |
| 366 | 9 702 20 | Raster H-125 | 1250 | 2012 | IN.201200630 | acad | 9 702 20 |
| 367 | 9 713 04 | National 1600 | 16000 | 2012 | IN.201200633 | acad | 9 713 04 |
| 368 | 9 715 06 | SE2-2000 | 20000 | 2012 | IN.201200069 | acad | 9 715 06 |
| 369 | 9 710 16 | SE4-1000 | 10000 | 2013 | IN.201300366 | acad | 9 710 16 |
| 370 | 9 708 31 | SE2-630 | 6300 | 2013 | | acad | 9 708 31 |
| 371 | 9 702 08/1 | UHS-170 | 1500 | 2013 | IN.201300511 | acad | 9 702 08/1 |
| 372 | 9 702 10 | SC2-125 | 1250 | 2013 | IN.201300651 | acad | 9 702 10 |
| 373 | 9 709 16/1 | SE2-800 | 8000 | 2013 | IN.201300685 | acad | 9 709 16/1 |
| 374 | 9 701 86 | SMS-10 | 100 | 2013 | IN.201300660 | acad | 9 701 86 |
| 375 | 9 706 35 | VP-400 | 4000 | 2014 | IN.201400070 | acad | 9 706 35 |
| 376 | 9 702 21 | SC2-160 | 1600 | 2014 | IN.201400079 | acad | 9 702 21 |
| 377 | 9 713 05 | LKM-1600 | 16000 | 2014 | IN.201400122 | acad | 9 713 05 |
| 378 | 9 708 32 | SE1-630 | 6300 | 2014 | IN.201400155 | acad | 9 708 32 |
| 379 | 9 711 12 | SE2-1200 | 12000 | 2015 | IN.201400228 | acad | 9 711 12 |
| 380 | 9 701 88 | C1-25 | 250 | 2015 | IN.201400191 | acad | 9 701 88 |
| 381 | 9 701 88/1 | C1-26 | 251 | 2015 | IN.201500121 | acad | 9 701 88/1 |
| 382 | 9 701 89 | C1-63 | 630 | 2015 | IN.201400195 | acad | 9 701 89 |
| 383 | 9 708 33 | SE2-630 | 630 | 2015 | IN.201500159 | acad | 9 708 33 |
| 384 | 9 701 92 | C1-40 | 400 | 2015 | IN.201500122 | acad | 9 701 92 |
| 385 | 9 701 90 | C1-16 | 160 | 2015 | IN.201400203 | acad | 9 701 90 |
| 386 | 9 701 91 | C1-10 | 100 | 2016 | IN.201400204 | acad | 9 701 91 |
| 387 | 9 704 33 | SK1-270 | 2700 | 2016 | IN.201400187 | acad | 9 704 33 |
| 388 | 9 701 87 | SK1-100 | 1000 | 2016 | IN.201400188 | acad | 9 701 87 |
| 389 | 9 702 22 | SK1-150 | 1500 | 2016 | IN.201400196 | acad | 9 702 22 |
| 390 | 9 711 09/1 | SE2-1200 | 12000 | 2016 | IN.201600005 | acad | 9 711 09/1 |
| 391 | 9 712 05 | SE4-1500 | 15000 | 2016 | IN.201600032 | acad | 9 712 05 |
| 392 | 9 705 35 | MPDK-300 | 3000 | 2016 | IN.201600081 | acad | 9 705 35 |
| 393 | 9 701 93 | C1-100 | 1000 | 2016 | IN.201600150 | acad+3D | 9 701 93 |
| 394 | 9 702 23 | C1-160 | 1600 | 2016 | IN.201600151 | acad | 9 702 23 |
| 395 | 9 701 94 | C1-25 | 250 | 2017 | IN.201600149 | acad | 9 701 94 |
| 396 | 9 701 95 | EPU-63 | 630 | 2017 | IN.201700020 | acad | 9 701 95 |
| 397 | 9 705 36 | MPDK-300 | 3000 | 2017 | IN.201700079 | acad | 9 705 36 |
| 398 | 9 705 37 | MANZONI-315 | 3150 | 2017 | IN.201700053 | acad | 9 705 37 |
| 399 | 9 705 38 | MPDK-300 | 3000 | 2018 | IN.201800072 | acad | 9 705 38 |
| 400 | 9 701 96 | EPU-63 | 630 | 2018 | IN201800098 | acad | 9 701 96 |
| 401 | 9 703 10 | ILR-200 | 2000 | 2018 | IN201800177 | acad | 9 703 10 |
| 402 | 9 702 24 | ESSA-120 | 1200 | 2019 | IN201900021 | acad | 9 702 24 |
| 403 | 9 702 25 | EPU-125 | 1250 | 2019 | IN201900052 | acad | 9 702 25 |
| 404 | 9 717 01 | SE2-2500 | 25000 | 2019 | IN201900067 | acad | 9 717 01 |
| 405 | 9 705 39 | SE1-300 | 3000 | 2020 | IN202000077 | acad+3D | 9 705 39 |

| | | | | | | | |
|-----|----------|---------|------|------|-------------|---------|----------|
| 406 | 9 701 97 | SE4-63 | 630 | 2020 | | acad+3D | 9 701 97 |
| 407 | 9 705 40 | SC2-315 | 3150 | 2020 | | acad+3D | 9 705 40 |
| | 9 706 36 | SC2-400 | 4000 | 2020 | IN201900396 | acad+3D | 9 706 36 |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |



Hydraulic presses

| Nr. | Inventory number | Typ | Nominal force (kN) | YOP | Engineering design (documentation records) | N. št. |
|-----|------------------|-------------------|--------------------|------|--|----------|
| 1 | 9 746 00 | SH1-25/30 | 30000 | 1999 | acad | 9 746 00 |
| 2 | 9 749 02 | SH3-1600 | 16000 | 2001 | acad | 9 749 02 |
| 3 | 9 747 01 | SH1-1500 | 15000 | 2008 | acad | 9 747 01 |
| 4 | 9 742 03 | HVO2-250 | 2500 | 2009 | acad | 9 742 03 |
| 5 | 9 743 01 | HFA-400 | 4000 | 2009 | acad | 9 743 01 |
| 6 | 9 741 18 | RAV-DH-150 | 1500 | 2009 | acad | |
| 7 | 9 744 01 | 630-M1104 | 6300 | 2009 | acad | 9 744 01 |
| 8 | 9 744 02 | TH-630 | 6300 | 2010 | acad | 9 744 02 |
| 9 | 9 743 02 | HFA-400 | 4000 | 2010 | acad | 9 743 02 |
| 10 | 9 741 19 | SH1-160 | 1600 | 2011 | acad | 9 741 19 |
| 11 | 9 740 04 | SH1-100 | 1000 | 2011 | acad | 9 740 04 |
| 12 | 9 740 05 | SH1-63 | 630 | 2011 | acad | 9 740 05 |
| 13 | 9 740 06 | SH1-63 (Ex) | 630 | 2012 | acad | 9 740 06 |
| 14 | 9 742 04 | SH1-250 (Ex) | 2500 | 2012 | acad | 9 742 04 |
| 15 | 9 743 03 | SH1-400 | 4000 | 2011 | acad | 9 743 03 |
| 16 | 9 743 04 | SH1-315 (Ex) | 3150 | 2012 | acad | 9 743 04 |
| 17 | 9 740 07 | SH1-50 (Ex) | 500 | 2012 | acad | 9 740 07 |
| 18 | 9 740 08 | SH1-10 (Ex) | 100 | 2012 | acad | 9 740 08 |
| 19 | 9 740 09 | SH1-63 | 630 | 2012 | acad | 9 740 09 |
| 20 | 9 744 03 | HVO2-630 | 6300 | 2012 | acad | 9 744 03 |
| 21 | 9 741 20 | SH1-160 | 1600 | 2012 | acad | 9 741 20 |
| 22 | 9 747 02 | DAH4-1000/630 | | 2012 | acad | 9 747 02 |
| 23 | 9 744 04 | SH1-500 | 5000 | 2013 | acad | 9 744 04 |
| 24 | 9 742 05 | HVO2-250 | 2500 | 2014 | acad | 9 742 05 |
| 24 | 9 741 21 | SH1-160 | 1600 | 2014 | acad | 9 741 21 |
| 25 | 9 740 10 | H1-50 (Ex)+voz. | 500 | 2015 | acad | 9 740 10 |
| 26 | 9 743 05 | H1-315 | 3150 | 2015 | acad | 9 743 05 |
| 27 | 9 743 06 | H1-350 (Ex)+2*voz | 3500 | 2015 | acad | 9 743 06 |
| 28 | 9 740 11 | H1-4 (Ex) | 40 | 2015 | acad | 9 740 11 |
| 29 | 9 743 08 | SH1-315 | 3150 | 2015 | acad | 9 743 08 |
| 30 | 9 740 12 | H1-63 | 630 | 2015 | acad | 9 740 12 |
| 31 | 9 743 07 | H1-315 | 3150 | 2015 | acad | 9 743 07 |
| 32 | 9 741 22 | H1-160 | 1600 | 2015 | acad | 9 741 22 |
| 33 | 9 740 17 | H1-2,5 (Ex) | 25 | 2015 | acad | 9 740 17 |
| 34 | 9 740 18 | H1-1 (Ex) | 10 | 2015 | acad | 9 740 18 |
| 35 | 9 740 14 | H1-6 (Ex) | 60 | 2015 | acad | 9 740 14 |
| | | H1-6 (Ex) | 60 | 2015 | acad | |
| 36 | 9 740 16 | H1-6 (Ex)+voz. | 60 | 2015 | acad | 9 740 16 |
| 37 | 9 740 13 | H1-25 | 250 | 2016 | acad | 9 740 13 |

| | | | | | | |
|----|----------|-----------------|-------|------|---------|----------|
| 38 | 9 740 15 | H1-30 (Ex)+voz. | 300 | 2016 | acad | 9 740 15 |
| 39 | 9 740 21 | SH1-80 | 800 | 2016 | acad | 9 740 21 |
| 40 | 9 740 22 | H1-40 | 400 | 2016 | acad | 9 740 22 |
| 41 | 9 740 19 | 3H1-12 (Ex) | 3x120 | 2016 | acad | 9 740 19 |
| 42 | 9 740 20 | H1-16 (Ex) | 160 | 2016 | acad | 9 740 20 |
| 43 | 9 742 06 | SH1-200 | 2000 | 2017 | acad | 9 742 06 |
| 44 | 9 740 23 | H1-12 | 120 | 2017 | acad | 9 740 23 |
| 45 | 9 740 24 | H1-40 | 400 | 2017 | acad | 9 740 24 |
| 46 | 9 740 25 | H1-60 | 600 | 2017 | acad | 9 740 25 |
| 47 | 9 741 23 | RAV-H-150 | 1500 | 2017 | acad | 9 741 23 |
| 48 | 9 748 01 | SH1-2000 | 20000 | 2017 | acad+3D | 9 748 01 |
| 49 | 9 740 26 | H1-80 | 800 | 2018 | acad | 9 740 26 |
| 50 | 9 744 05 | SH2-500 | 5000 | 2018 | acad+3D | 9 744 05 |
| 51 | 9 740 27 | SH1-63 (Ex) | 630 | 2018 | acad+3D | 9 740 27 |
| 52 | 9 744 06 | H1-500 | 5000 | 2018 | acad+3D | 9 744 06 |
| 53 | 9 743 09 | ILR-315 | 3150 | 2018 | acad | 9 743 09 |
| 54 | 9 743 10 | ILR-400 | 4000 | 2018 | acad | 9 743 10 |
| 55 | 9 748 02 | SH1-2000 | 20000 | 2019 | acad+3D | 9 748 02 |
| | | | | | | 0 |

LINES

| Nr. | Inventory number | Presses | YOP | IN. (ON.) | Engineering design (documentation records) | Nr. |
|-----|------------------|---------------------|------|-----------|--|----------|
| 1 | 9 732 00 | | 1979 | | manual | 9 732 00 |
| 2 | 9 732 01 | | 1983 | | manual | 9 732 01 |
| 3 | 9 732 02 | | 1984 | | manual | 9 732 02 |
| 4 | 9 732 03 | | | | manual | 9 732 03 |
| 5 | 9 732 04 | | 1985 | | manual | 9 732 04 |
| 6 | 9 732 05 | | | | manual | 9 732 05 |
| 7 | 9 732 06 | | 1985 | | manual | 9 732 06 |
| 8 | 9 732 07 | | 1986 | | manual | 9 732 07 |
| 9 | 9 732 08 | | 1987 | | manual | 9 732 08 |
| 10 | 9 732 09 | | 1988 | | manual | 9 732 09 |
| 11 | 9 732 10 | | | | manual | 9 732 10 |
| 12 | 9 732 11 | | 1988 | | manual | 9 732 11 |
| 13 | 9 732 12 | | 1988 | | manual | 9 732 12 |
| 14 | 9 732 13 | | 1990 | | manual | 9 732 13 |
| 15 | 9 732 14 | | 1990 | | manual | 9 732 14 |
| 16 | 9 732 15 | | 1990 | | manual | 9 732 15 |
| 17 | 9 732 16 | | 1994 | | manual | 9 732 16 |
| 18 | 9 732 17 | | 1994 | | manual | 9 732 17 |
| 19 | 9 732 18 | | 1995 | | manual | 9 732 18 |
| 20 | 9 732 18 | | 1996 | | manual | 9 732 18 |
| 21 | 9 732 19 | SC1-100_9 701 31 | 1996 | | manual | 9 732 19 |
| 22 | 9 732 20 | RLC-200_9 703 05 | | | manual | 9 732 20 |
| 23 | 9 732 21 | | | | manual | 9 732 21 |
| 24 | 9 732 22 | | 1997 | | manual | 9 732 22 |
| 25 | 9 732 23 | SC2-600_9 708 17 | 1997 | | manual | 9 732 23 |
| 26 | 9 732 24 | | | | manual | 9 732 24 |
| 27 | 9 732 25 | | 1997 | ON.80043 | acad | 9 732 25 |
| 28 | 9 732 26 | SH1-25/30_9 746 00 | | ON.10010 | acad | 9 732 26 |
| 29 | 9 732 28 | SC2-320_9 705 17 | 1998 | ON.90092 | | 9 732 28 |
| 30 | 9 732 29 | SE4-1500_9 712 02 | 1999 | | | 9 732 29 |
| | | SE4-1000_9 710 18 | | | | |
| | | 3x SE4-800_9 709 11 | | | | |
| 31 | 9 732 30 | SC1-300_9 705 18 | 2000 | ON.10075 | | 9 732 30 |
| | | SC2-400_9 706 18 | | | | |
| | | C1-100_9 701 75 | | | | |
| 32 | 9 732 31 | | 2000 | | | 9 732 31 |
| 33 | 9 732 32 | SC2-200_9 703 07 | 2001 | ON.20073 | | 9 732 32 |
| 34 | 9 732 33 | SC2-400_9 706 19 | 2001 | ON.30001 | | 9 732 33 |
| | | SC2-400_9 706 20 | | | | |

| | | | | | | |
|----|---------------|--------------------|------|------------|------|---------------|
| | | C1-100_9 701 77 | | | | |
| 35 | 9 732 33/3 | SC2-400_9 706 19 | 2001 | ON.30041 | | 9 732 33/3 |
| | | SC2-400_9 706 20 | | | | |
| | | C1-100_9 701 77 | | | | |
| 36 | 9 732 34 | SC2-600_9 708 20 | 2001 | ON.30025 | acad | 9 732 34 |
| 37 | 9 732 35 | | 2001 | | | 9 732 35 |
| 38 | 9 732 36 | | 2001 | ON.30044 | acad | 9 732 36 |
| 39 | 9 732 37 | SC2-500_9 707 23 | 2002 | ON.40027 | acad | 9 732 37 |
| 40 | 9 732 38 | | 2002 | ON.40044 | acad | 9 732 38 |
| 41 | 9 732 39 | SC2-400_9 706 21 | 2002 | ON.40070 | acad | 9 732 39 |
| | | SC2-500_9 707 24 | | | | |
| | | C1-100_9 701 80 | | | | |
| 42 | 9 732 40 | 4x C1-125_9 702 13 | 2003 | ON.50001 | | 9 732 40 |
| | | 1x C1-250_9 704 26 | | | | |
| | | 3x C1-315_9 705 21 | | | | |
| 43 | 9 732 41 | DA-500/300-SE2-630 | 2003 | ON.50006-8 | acad | 9 732 41 |
| | | SE2-500_9 707 25 | | | acad | |
| | | SE2-630_9 708 27 | | | acad | |
| 44 | 9 732 42 | | 2003 | ON.50011 | acad | 9 732 42 |
| | | | | | acad | |
| 45 | 9 732 43 | SE2-800_9 709 15 | 2004 | ON.50013 | acad | 9 732 43 |
| 46 | 9 732 44 | SC2-320_9 705 22 | 2004 | ON.60001-2 | acad | 9 732 44 |
| 47 | 9 732 45 | SC2-600_9 708 24 | 2004 | ON.60004 | acad | 9 732 45 |
| | | | | | | |
| 48 | 9 732 46 | SC2-250_9 704 27 | 2004 | ON.60003 | acad | 9 732 46 |
| 49 | 9 732 47 | SC2-600_9 708 25 | 2004 | ON.60005 | acad | 9 732 47 |
| | | | | | | |
| 50 | 9 732 48 | SC1-300_9 705 23 | 2005 | ON.60008 | acad | 9 732 48 |
| | | SC1-300_9 705 24 | | | acad | |
| | | C1-80_9 701 81 | | | acad | |
| 51 | 9 732 49 | SC1-300_9 705 25 | 2005 | ON.60186 | acad | 9 732 49 |
| | | SC1-300_9 705 26 | | | acad | |
| | | C1-80_9 701 82 | | | acad | |
| 52 | 9 732 50 | SE4-1000_9 710 20 | 2005 | ON.70004 | acad | 9 732 50 |
| | | | | | acad | |
| 53 | 9 732 51 | | 2005 | ON.70002 | acad | 9 732 51 |
| 54 | 9 732 52 | | 2005 | ON.70002 | acad | 9 732 52 |
| 55 | 9 732 53 | | 2005 | ON.70002 | acad | 9 732 53 |
| 56 | 9 732 54 | | 2005 | | acad | 9 732 54 |
| 57 | 9 732 55 | SE4-315_9 705 27 | 2006 | ON.70005 | acad | 9 732 55 |
| | | SE4-250_9 704 28 | | | acad | |
| 58 | 9 732 56 | SC2-500_9 707 27 | | ON.70011 | acad | 9 732 56 |
| 59 | 9 732 57 | SE2-1000_9 710 24 | 2006 | ON.80005 | acad | 9 732 57 |
| | | SE2-500_9 707 28 | | ON.80006 | acad | |
| | | SE2-400_9 706 25 | | ON.80007 | acad | |
| | | SE2-400_9 706 26 | | ON.80008 | acad | |
| | | SE2-800_9 709 17 | | ON.80009 | acad | |
| 60 | 9 732 58 | SC2-400_9 706 24 | 2007 | ON.80013 | acad | 9 732 58 |
| | | SC1-400_9 706 28 | 2009 | | acad | |

| | | | | | | |
|----|----------|--|------|----------------|------|----------|
| | | SC1-400_9 706 29 | | | acad | |
| | | SE2-100_9 701 83 | | | acad | |
| 61 | 9 732 59 | SE2-800_9 709 18 | 2007 | IN.200700006 | acad | 9 732 59 |
| | | SE2-500_9 707 29 | | IN.200700005 | acad | |
| | | 2x SE2-400_9 706 30 | | IN.200700003-4 | acad | |
| 62 | 9 732 60 | SC2-500_9 707 30 | 2007 | IN.200700183 | acad | 9 732 60 |
| 63 | 9 732 61 | SE2-1200_9 711 09 | 2007 | IN.200700092 | acad | 9 732 61 |
| 64 | 9 732 62 | SC2-400_9 706 31 | 2007 | IN.200700217 | acad | 9 732 62 |
| | | SC1-300_9 705 30 | | | acad | |
| | | SC1-300_9 705 31 | | | acad | |
| | | C1-80_9 701 84 | | | acad | |
| 65 | 9 732 63 | C1-315_9 705 32 | | IN.200700218 | acad | 9 732 63 |
| | | C1-315_9 705 33 | | | acad | |
| | | C1-315_9 705 34 | | | acad | |
| | | C1-125_9 702 14 | | | acad | |
| | | C1-250_9 704 31 | | | acad | |
| | | C1-125_9 702 15 | | | acad | |
| | | C1-125_9 702 16 | | | acad | |
| | | C1-125_9 702 17 | | | acad | |
| 66 | 9 732 64 | SE2-250_9 704 30 | 2007 | IN.200700181 | acad | 9 732 64 |
| 67 | 9 732 65 | SE2-400_9 706 32 | 2008 | IN.200800256 | acad | 9 732 65 |
| | | | | | acad | |
| | | | | | acad | |
| | | | | | acad | |
| | | | | | acad | |
| | | | | | acad | |
| | | | | | acad | |
| 69 | 9 732 67 | RAV-DH-150_9 741 18 | 2009 | IN.200900307 | acad | 9 732 67 |
| 70 | 9 732 68 | 3PL Vipond 9 732 30 8PL Vipond 9 732 40 | 2010 | IN.201000315 | acad | 9 732 68 |
| 71 | 9 732 69 | SE2-400_9 706 33 | 2010 | IN.201000564 | acad | 9 732 69 |
| | | | | | acad | |
| | | | | | acad | |
| 72 | 9 732 70 | SC2-80_9 701 85 | 2010 | IN.201000737 | acad | 9 732 70 |
| | | | | | acad | |
| 73 | 9 732 71 | SE4-2500_9 717 04 | 2011 | IN.201100072 | acad | 9 732 71 |
| | | | | | acad | |
| 74 | 9 732 72 | SE4-1000_9 710 25 | 2011 | IN.201100071 | acad | 9 732 72 |
| | | | | | acad | |
| 75 | 9 732 73 | SE2-1250_9 711 03 | 2011 | IN.201000239 | acad | 9 732 73 |
| | | | | | acad | |
| 76 | 9 732 74 | SC2-200_9 703 09 | 2012 | IN.201200070 | acad | 9 732 74 |
| 77 | 9 732 75 | | 2012 | IN.201200294 | acad | 9 732 75 |
| | | | | | | 0 |

PRESSES

Electrical
processing

| Nr. | Inventory number | Year of repair |
|-----|------------------|----------------|
| 1 | | |
| 2 | 9 708 22 | |
| 3 | | |
| 4 | | |
| 5 | | 1998 |
| 6 | | 1998 |
| 7 | | 2001 |
| 8 | | 2001 |
| 9 | | 2001 |
| 10 | | 2001 |
| 11 | | 2001 |
| 12 | | 2001 |
| 13 | | 2001 |
| 14 | | 2002 |
| 15 | | 2002 |
| 16 | 9 704 08 | 2002 |
| 17 | | 2002 |
| 18 | | 2002 |
| 19 | | 2002 |
| 20 | | 2002 |
| 21 | | 2002 |
| 22 | | 2003 |
| 23 | | 2004 |
| 24 | | 2004 |
| 25 | | 2005 |
| 26 | | 2005 |
| 27 | 9 704 24 | 2009 |
| 28 | | |
| 29 | | |
| 30 | | |
| 31 | | |
| 32 | | |
| 33 | | |
| 34 | | |
| 35 | | |
| 36 | | |
| 37 | | |
| 38 | | |

PRESSES

Service repair

| Nr. | Number | Nominal force (kN) | Year of service (repair) | IN. (ON.) | Engineering design (documentation records) | Number |
|-----|-------------|--------------------|--------------------------|--------------|--|-------------|
| 1 | 9 700 2449 | | 2009 | IN.200900167 | acad | 9 700 2449 |
| 2 | 9 700 2496 | | 2009 | IN.200900341 | acad | 9 700 2496 |
| 3 | 9 704 27 | | 2010 | IN.200900357 | acad | 9 704 27 |
| 4 | 9 708 27 | | 2010 | IN.200900359 | acad | 9 708 27 |
| 5 | 9 704 13 | | 2010 | IN.201000078 | acad | 9 704 13 |
| 6 | 9 700 2523 | | 2010 | IN.201000298 | acad | 9 700 2523 |
| 7 | 89 700 2533 | | 2010 | IN.201000392 | acad | 89 700 2533 |
| 8 | 89 700 2555 | 1250 | 2010 | IN.201000414 | acad | 89 700 2555 |
| 9 | 89 700 2564 | | 2010 | IN.201000437 | acad | 89 700 2564 |
| 10 | 9 701 71 | 1000 | 2010 | IN.201000475 | acad | 9 701 71 |
| 11 | 9 700 2660 | | 2012 | IN.201200562 | acad | 9 700 2660 |
| 12 | 9 700 2686 | | 2013 | IN.201300095 | acad | 9 700 2686 |
| 13 | 89 700 2687 | | 2013 | IN.201300231 | acad | 89 700 2687 |
| 14 | 89 700 2701 | 3500 | 2013 | IN.201300405 | acad | 89 700 2701 |
| 15 | 89 700 2714 | | 2013 | IN.201300506 | acad | 89 700 2714 |
| 16 | 89 700 2748 | | 2013 | IN.201300413 | acad | 89 700 2748 |
| 17 | 9 700 2691 | 10000 | 2012 | IN.201200683 | acad | 9 700 2691 |
| 18 | 89 700 2709 | 10000 | 2013 | IN.201300523 | acad | 89 700 2709 |
| 19 | 89 700 2801 | 2000 | 2014 | IN.201400003 | acad | 89 700 2801 |
| 20 | 89 700 2807 | | 2014 | IN.201400163 | acad | 89 700 2807 |
| 21 | 700 2832 | | 2014 | IN.201400094 | acad | 700 2832 |
| 22 | 700 2834 | | 2014 | IN.201400119 | acad | 700 2834 |
| 23 | 89 700 2856 | 3150 | 2014 | IN.201400218 | acad | 89 700 2856 |
| 24 | 9 700 2858 | 750 | 2015 | IN.201500005 | acad | 9 700 2858 |
| 25 | 9 700 2931 | | 2015 | IN.201500050 | acad | 9 700 2931 |
| 26 | 700 2941 | | 2015 | IN.201500119 | acad | 700 2941 |
| 27 | 89 700 2947 | 1500 | 2015 | IN.201500173 | acad | 89 700 2947 |
| 28 | 9 701 28 | 850 | 2016 | IN.201600002 | acad | 9 701 28 |
| 29 | 89 700 2959 | 5000 | 2016 | IN.201600007 | acad | 89 700 2959 |
| 30 | 89 700 2960 | | 2016 | IN.201600037 | acad | 89 700 2960 |
| 31 | 89 700 2961 | | 2016 | IN.201600042 | acad | 89 700 2961 |
| 32 | 89 700 2978 | | 2016 | IN.201600064 | acad | 89 700 2978 |
| 33 | 9 700 2980 | 5000 | 2016 | IN.201600068 | acad | 9 700 2980 |
| 34 | 700 2996 | | 2016 | IN.201600147 | acad | 700 2996 |
| 35 | 89 700 3053 | 800 | 2018 | IN.201800116 | acad | 89 700 3053 |